From:

Steve Demczak

To:

Oakley, Dennis; Suzanne Steab 4/1/2010 12:58 PM

Date: Subject:

Insp. March Attachments: 20100401121515.pdf



The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

Representatives Present During the Inspection: Company Dennis Oakley Environmental Engineer OGM Steve Demczak Environmental Scientist III

Inspection Report

Permit Number:	C0150017
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, March 16, 2010
Start Date/Time:	3/16/2010 10:00:00 AM
End Date/Time:	3/16/2010 1:00:00 PM
Last Inspection:	Tuesday, February 16, 2010

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 30's, Mostly Snow Covered

InspectionID Report Number: 2309

Types of Operations

Accepted by: jhelfric 4/1/2010

Permitee: PacifiCorp

Operator: ENERGY WEST MINING CO

Site: DES BEE DOVE MINE

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

Total Permitted	134.31
Total Disturbed	36.02
Phase I	43.40
Phase II	
Phase III	2.52

Mineral Ownership

✓ Federal	✓ Underground
☐ State	Surface
☐ County	Loadout
☑ Fee	Processing
Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations were issued

Inspector's Signature:

Steve Demozak, Environmental Scientist III

Date

Monday, March 29, 2010

Sieve Demczak, Environmental

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Utah!

Permit Number: C0150017 Inspection Type: PARTIAL

Inspection Continuation Sheet

Inspection Date: Tuesday, March 16, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
 Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Commont	Enforcemen
1.	Permits, Change, Transfer, Renewal, Sale	Evaluateu ✓		Comment ✓	Enlorcemen
2.	Signs and Markers	<u> </u>		V	
3.	Topsoil	<u> </u>		<u> </u>	
4.a	Hydrologic Balance: Diversions	<u> </u>	П	<u> </u>	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments		П	$\overline{\overline{n}}$	$\overline{\Box}$
4.c	Hydrologic Balance: Other Sediment Control Measures	<u> </u>		<u> </u>	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments		П	$\overline{\Box}$	$\overline{}$
8.	Noncoal Waste	<u> </u>		V	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	V		V	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	V		✓	
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other	П			П

Permit Number: C0150017 Inspection Type: PARTIAL

Inspection Date: Tuesday, March 16, 2010

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The DOGM permit will expire on Aug.30, 2010.

2. Signs and Markers

The identification sign is located on the trail to the property.

3. Topsoil

All topsoil was used in reclamation.

4.a Hydrologic Balance: Diversions

The diversions are snow covered. The snow is melting at a slow rate.

4.c Hydrologic Balance: Other Sediment Control Measures

The entire site is pocked to prevent sediment from leaving the reclaim area.

8. Noncoal Waste

The site is snow covered and should not contain non-coal waste materials.

10. Slides and Other Damage

No slides or damage was noticed during the inspection.

12. Backfilling And Grading

The site is completely backfilled and graded.